



Annual Statement

Glendale School District #77 certifies the following:

Responsible Persons

The person responsible for implementing and administering the Healthy and Safe Schools (HASS) Plan is:

Name: Clinton Crites
Position Title: Maintenance Director
Phone Number: 541-832-1801
Email Address: ccrites@glendale.k12.or.us
Mailing Address: PO Box E Glendale Or, 97442

The person who is the designated Integrated Pest Management (IPM) Coordinator is:

Name: Clinton Crites
Position Title: Maintenance Director
Phone Number: 541-832-1801
Email Address: ccrites@glendale.k12.or.us
Mailing Address: PO Box E Glendale Or, 97442

The person responsible for Asbestos Hazard Emergency Response Act (AHERA) information is:

Name: Clinton Crites
Position Title: Maintenance Director
Phone Number: 541-832-1801
Email Address: ccrites@glendale.k12.or.us
Mailing Address: PO Box E Glendale Or, 97442

Copies of the Healthy and Safe Schools Plan

Copies of the plan are available at each of the following locations:

- Glendale School District office 10598 Azalea Glen Rd Glendale Or, 97442
- Glendale School District #77 website <http://www.glendale.k12.or.us/>

Testing Certification

Glendale School District #77 certifies that it is in compliance with all plan components, including any and all testing required by any part of the plan.

Testing Results

Glendale School District #77 is current with all required testing as of the date of this document. Test results can be found on the Glendale School District website at <http://www.glendale.k12.or.us/>. The Glendale School District will also use current district email lists or communications programs to provide final test results to staff, students, parents of minor students, and other members of their community. This includes providing actual final test results or providing direct access to final test results through links in the communications. Please contact Delwin Johnson to be added to current district email lists and programs. Specific test results can be found as follows:

- Lead in Water: <http://www.glendale.k12.or.us/>
- Radon: <http://www.glendale.k12.or.us/>
- Asbestos <http://www.glendale.k12.or.us/>

Website Link Maintenance

Glendale School District #77 certifies that all website links for plan information and test results are current and functional.

Major Exposure Reduction Activities

No Major Exposure Reduction Activities were conducted during the past year.

Radon Testing Summary (Optional)

Glendale School District #77 has completed radon testing at the following buildings in 2020 and is providing the following summary:

Facility Name	Building Identification Number (BIN)	Number of radon tests conducted	Number of tests that exceed limits	Number of tests that exceed limits after remediation	Number of sites where remediation is still in process
Glendale Elementary School	20000100	23	0	0	0
Glendale Sr high School	20000102	25	0	0	0
Glendale Jr High School	20000101	8	0	0	0
Glendale Jr Sr High School Library	20000103	4	0	0	0

I certify that the above information is true and accurate to the best of my knowledge.

Clinton Crites	Maintenance Director	5/22/2025
	Title	Date of Annual Certification